

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R00050080157-0 9

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 3-28-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPEN
NUMBERBUY OUT
CODE NO.ACCT. OR
W.O. NO.

S.O. NO.

322

12

0

23

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED REJECTED

REMARKS

12

738340-2 Letter Access Cover

11

Stores

I.D. #4002689

RECEIVED
BY

HMC-105

INSPECTED
BY

DATE 3-28-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11728

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPEN
NUMBER

DATE REC'D. 3-28-57

P.O. NO.

VENDOR PACKING SLIP NO.

ACCT. OR
W.O. NO.

S.O. NO.

322

14

0

4

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED REJECTED

REMARKS

4

738268 Spectr SW Actuator

4

I.D. #4002625

Approved For Release 2000/04/18 : CIA-RDP81B00879R00050080157-0

RECEIVED

HMC-105

INSPECTED
BY

DATE 3-29-57

REJECTS RETURNED
ON SHIP. MEMO NO.